

United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

September 24, 2013

Ms. Gail Eddings Allegheny County Health Department Department of Air Quality 301 Thirty-Ninth Street Pittsburgh, PA 15201

RECEIVED

OCT 17 2013

Division Linear (UAPOO)

Subject: USS Reference Number: 13-0185

ACHD Reference Number: N/A

Sulfur Plant

USS Clairton Works

Dear Gail Eddings,

The attached form confirms our verbal report of the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Thomas E. Schumacher

Plant Manager Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 13-0185
ACHD Reference Number: N/A

- 2. Date & Time of Breakdown: Date: 09/23/13 Time: 0500 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: Sulfur Plant
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: During an approximate 1 week period, the C658 sulfur plant vacuum axi will be unavailable for service to perform maintenance. The C658 Axi is a redundant piece of equipment. The spare 101J Axi will carry the full load. Sulfur Plant performance will not be affected and emissions will not increase due to this work.
- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 The spare 101J Axi will carry the full load. No
 environmental impact is expected.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
 - C. Amount of each type emitted (or likely to be emitted). N/A
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

 The spare 101J Axi will carry the full gas flow to the plant.
- 10. Facility back in operation Date: Time: hours

Reviewed	by (i Cees In Datin	Date 9-35-13
	Coleen M. Davis	

Senior Environmental Control Engineer Phone: 412-233-1015